



NOTE1: in v1 of PCB there is 1k resistor instead of C11

NOTE2: in v1 of PCB R14 is 445 and R18 is 145

NOTE3: original U5 and U6 are not available, only R25 is available. Because of that, it's necessary to remove R25 & R26 !

Components references not related to manufacturers ones. Standard datasheet schematics etc).